

GST BOCES

District:

Elmira Heights

Initial Fire Inspection Report

School/Building:

High School

Page 1 of 1

Date: 5-2-12

(12) Emergency lights
(30) Exit signs
(31) Elec. Panel Records

Code	Classroom/area or building or general room description	Res. Will	Ext. Sign (1)	Ext. Corrid. Use (2)	Ignition Source (3)	Two feet rule (cell in Cor. 5)	Deco too close to door/paper on dr. (5)	Surge to surge (6)	Deco hanging from ceiling (7)	Deco over exit way (8)	Excessive Decorations in Corridor (9)	Evacuate instructions (10)	Firm Storage (11)	Corridor (stage or diked) (12)	Housekeeping (13)	Door blocked (wedge) (14)	12E1/ school appliances (oven, microwaves etc.) (15)	17C2 Vision panel obstructed	1502 Fabrics/curtains fire res (17)	12E1 UL listing (18)	12A1, 12G1 Electrical panel blocked (19)	15A2, 17A3 Exit path in room blocked (20)	12K1 Exposed wires (21)	23D2 Elevator signs/certs (22)	1712 Tactile signs at stairs (23)	11A2 Parking in fire lane (24)	BVRCRA No C of O posted (25)	9F2 Combust. in mech./boiler/elec (26)	11E1 Blocked/missing fire Exit (27)	20A1, 20B1 No Hot work area (28)	(17H, 23A) Emergency lights	17D2, 17L1 Exit signs (30)	08E2 Elec. Panel Records (31)																					
7																																																						
5																																																						
Hobby Room																																																						
16																																																						
17																																																						
22																																																						

Comments/clarifications (Note: The above table indicates frequent non-conformances only and is not all inclusive)

reference to "0" clear space either side of exit is no longer in code; enforce no decorations on door & 20% in hallways

Joe

K-10

District: Elmira Heights

School/Building: Cohen - Middle

Date: 5-2-12

(128) Light (128)
(30) Exit Signs (30)
(31) Elec. Panel Records (31)

Code	Building or general room description	Classifications	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28
229	Res. Wk	Res. Wk	X																											
227	Subst Storage	Subst Storage																												
229																														
233																														
129																														

Comments/clarifications (Note: The above table indicates frequent non-conformances only and is not all inclusive)

Reference to 10' clear space either side of exit is no longer in code; enforce no decorations on door & 20% in hallways