



STATE OF NEW YORK
DEPARTMENT OF TRANSPORTATION
ALBANY, N.Y. 12232

WWW.DOT.NY.GOV

JOAN McDONALD
COMMISSIONER

ANDREW M. CUOMO
GOVERNOR

M-1

May 17, 2013

OPERATOR ID 02917

ELMIRA HEIGHTS CENTRAL SCHOOL
100 ROBINWOOD AVE
ELMIRA HEIGHTS, NY 14903-1598

Dear Motor Carrier:

Enclosed is the annual New York State Department of Transportation Bus Inspection System Operator Profile that summarizes the results of vehicle inspections performed on your fleet by the Department during the last State Fiscal Year (April 1, 2012 to March 31, 2013). For regularly scheduled inspections, the profile identifies the number and percentage of vehicles that passed or were placed Out-of-Service (OOS) due to one or more OOS defects. It is the Department's continued goal to have all operators pass at least 90% of their scheduled safety inspections. The statewide average OOS rate is 5.8%.

For those operators with at least ten or more regular inspections, and whose OOS rate is 25% or greater you are now put on notice that you fall under the Department's enforcement program. If you have not been notified already, you will be contacted to address your unacceptable performance. Actions may include civil penalties, unannounced vehicle inspections, denial of B & C privileges, compliance reviews or other corrective actions.

Operators that have a passing rate of less than 90%, it is requested that your organization examine the enclosed profile inspection data and immediately update your maintenance program to reduce your OOS Rate to meet our goals. Your Regional Bus Inspection Program Supervisor is available to review the actions being taken and provide assistance if necessary.

We congratulate those operators who have achieved the goal of a 90% or greater pass rate. Your commendable performance indicates a strong dedication to safety and a commitment to sound maintenance standards and practices.

For additional program information please visit: <https://www.dot.ny.gov/divisions/operating/osss/bus>

Sincerely,

A handwritten signature in black ink, appearing to read 'Lawrence Scotto', written over a horizontal line.

Lawrence Scotto, Acting Director
Passenger Carrier Safety Bureau

Enclosures

cc: Regional Bus Program Supervisor

NYS DEPARTMENT OF TRANSPORTATION
BUS INSPECTION SYSTEM
OPERATOR PROFILE

***** PROFILE PERIOD: INSPECTION PERIOD:
* OPERATOR # * 2012-04-01 THRU 2013-03-31 2012-04-03 THRU 2013-02-25
* 2917 *
* OOS 0.0 % * REGION : 04 TYPE(S) OF SERVICE: 1
* PM 96.9 % *

ELMIRA HEIGHTS CENTRAL SCHOOL
100 ROBINWOOD AVE
ELMIRA HEIGHTS NY 14903-1598

INSP. SUMMARY	TOTAL	PASS	PCT
REGULAR (TYPE 1)	32	32	100.0 %
REINSPECT (TYPE 2)	0	0	0.0 %
INITIAL (TYPE 9)	0	0	0.0 %
RANDOM (TYPE 0)	0	0	0.0 %
TOTAL OF TYPES 0,1,2,9	32		
ACCIDENT (TYPE 3)	0		0.0 %
TEMP. OOS (TYPE 4)	0		0.0 %
PERM. OOS (TYPE 5)	6		18.8 %
FLEET (TYPE 6)	0		0.0 %
NON-PRESENT (TYPE 7)	0		0.0 %
OTHER (TYPE 8)	0		0.0 %
TOTAL OF TYPES 3-8	6		

B+C PRIVILEGE CODE = GRANT

RESULTS OF REGULAR INSPECTIONS

REGULAR INSPECTION DATA	TOT	PCT
TOTAL INSP:	32	
TOTAL INSP PASSED:	32	100.0 %
TOTAL INSP W/"A" DEFECT:	0	0.0 %
TOTAL INSP W/"B" DEFECT:	0	0.0 %
TOTAL INSP W/"C" DEFECT:	0	0.0 %
TOTAL INSP W/A, B, OR C:	0	0.0 %
TOTAL INSP W/NO DEFECTS:	32	100.0 %
TOTAL INSP OOS W/A DEFECT:	0	0.0 %
TOTAL INSP OOS:	0	0.0 %

DEFECT DATA	PCT OF TOTAL 0,1,2,9
TOTAL DEFECTS:	0
TOTAL "A" DEFECTS:	0
TOTAL "B" DEFECTS:	0
TOTAL "C" DEFECTS:	0
TOTAL "OTHER" DEFECTS:	0
TOTAL HWY OPN PROHIBITED:	0
AVERAGE DEFECTS/INSP:	0.0
AVERAGE "A" DEFECTS/INSP:	0.0
AVERAGE "B" DEFECTS/INSP:	0.0
AVERAGE "C" DEFECTS/INSP:	0.0

DEFECT SUMMARY - REGULAR INSPECTIONS

ITEM	DESCRIPTION	TOTAL
------	-------------	-------

"A" DEFECTS:

NYS DEPARTMENT OF TRANSPORTATION
 BUS INSPECTION SYSTEM
 OPERATOR PROFILE - PREVENTATIVE MAINTENANCE SECTION

***** PROFILE PERIOD: INSPECTION PERIOD:
 * OPERATOR # * 2012-04-01 THRU 2013-03-31 2012-04-03 THRU 2013-02-25
 * 2917 *
 ***** REGION : 04

ELMIRA HEIGHTS CENTRAL SCHOOL
 100 ROBINWOOD AVE
 ELMIRA HEIGHTS NY 14903-1598

	NUMBER

NUMBER OF VEHICLES INSPECTED:	17
TOTAL NUMBER OF TYPE 1 INSPECTIONS:	32

 SELECTED PM CODES SUMMARY SECTION

	NUMBER	PCT.
	-----	-----
TOTAL INSP. WITH 1 OR MORE "A" PM DEFECTS:	0	0.0%
TOTAL INSP. WITH 1 OR MORE "B" PM DEFECTS:	0	0.0%
TOTAL INSP. WITH 1 OR MORE "C" PM DEFECTS:	0	0.0%
TOTAL INSP. WITH 3 OR MORE "A" PM DEFECTS:	0	0.0%
TOTAL INSP. WITH 3 OR MORE "B" PM DEFECTS:	0	0.0%
TOTAL INSP. WITH 3 OR MORE "C" PM DEFECTS:	0	0.0%
TOTAL "A" DEFECTS:	0	
TOTAL "B" DEFECTS:	0	
TOTAL "C" DEFECTS:	0	
TOTAL:	0	

 PREVENTATIVE CODES SUMMARY SECTION

ITEM	DESCRIPTION	TOTAL	PCT %
-----	-----	-----	-----
53.00	MAINTENANCE & RECORDS: OK	31	96.9
53.03	MAINTENANCE & RECORDS: PMI EXCEEDED	1	3.1

NUMBER OF PM CODES 5302 THRU 5309: 1
 NUMBER OF PM CODES (5300 THRU 5309) - 5301: 32

PM CODES PERCENTAGE
 5302 THRU 5309 / (5300 THRU 5309) - 5301 = 3.1 %

D03
CSBU34

NYS DOT Bus Inspection System

05/29/13

Operator Profile Inspection Summary Part I

Operator: 2917 Profile Period: 04/01/12 - 03/31/13

ELMIRA HEIGHTS CENTRAL SCHOOL Type(s) of Service: 1

100 ROBINWOOD AVE NYS DOT Region: 04

ELMIRA HEIGHTS NY 14903 - 1598 Insp #: 1122

B-C Privilege Code: GRANT No. Veh. Insp. (Types 1 and 9): 17

Inspection Summary:	Tot	Pass	Pct	Defect Data	
Regular Inspections:	32	32	100.0	Total Defects:	0
Reinspections:	0	0	0.0	Total "A" Defects:	0
Initial Inspections:	0	0	0.0	Total "B" Defects:	0
Random Inspections:				Total "C" Defects:	0
Regular Inspection Data	Tot	Pct		Total "Other" Defects:	0
Total Inspections:	32			Total Hwy Opn Prohibited:	0
Total Insp Passed:	32	100.0		Inspection Statistics	
Total Insp w/"A" Defect:	0	0.0		Average Defects/Insp:	0.0
Total Insp w/"B" Defect:	0	0.0		Average "A" Defects/Insp:	0.0
Total Insp w/"C" Defect:	0	0.0		Average "B" Defects/Insp:	0.0
Total Insp w/A, B, or C:	0	0.0		Average "C" Defects/Insp:	0.0
Total Insp w/No Defects:	32	100.0			
Total Insp OOS:	0	0.0			

F1=Help F2=Cancel F5=Pm F6=Diesel F9=Points F10=PartII

Operator: 2917 Profile Period: 04/01/12 - 03/31/13

ELMIRA HEIGHTS CENTRAL SCHOOL	Type(s) of Service: 1
100 ROBINWOOD AVE	NYSDOT Region: 04
ELMIRA HEIGHTS NY 14903 - 1598	NYSDOT Insp #: 1122
B-C Privilege Code: GRANT	No. Veh. Insp. (Types 1 and 9): 17
	Total "A" Rated Defects: 0

Item	Description	Total
------	-------------	-------

- "A" DEFECTS:
- "B" DEFECTS:
- "C" DEFECTS:
- "OTHER" DEFECTS:
- "INSPECTION POINTS NOT COUNTED AS" DEFECTS:

F1=Help F2=Cancel F5=Pm F6=Diesel F7=Up F8=Down F9=PartI F10=PartII

BUS NYSDOT Bus Inspection System 05/29/13
 CSBU49 Operator Profile Inspection Summary Part II
 Operator: 2917 Profile Period: 04/01/12 - 03/31/13
 ELMIRA HEIGHTS CENTRAL SCHOOL Type(s) of Service: 1
 100 ROBINWOOD AVE NYSDOT Region: 04
 ELMIRA HEIGHTS NY 14903 - 1598 Insp #: 1122
 B-C Privilege Code: GRANT No. Veh. Insp. (Types 1 and 9): 17

Inspection Summary:			Tot	Pass	Pct
Regular Inspections-(Type 1):			32	32	100.0
Reinspections- (Type 2):			0	0	0.0
Initial Inspections-(Type 9):			0	0	0.0
Random Inspections- (Type 0):			0	0	0.0
Total of Types 0,1,2,9:			32		
			Tot	PCT of Total 0,1,2,9	
Accident Insp.- (Type 3):			0		.0
Temp. OOS Insp.- (Type 4):			0		.0
Perm. OOS Insp.- (Type 5):			0		.0
Fleet Inspections- (Type 6):			0		.0
Non-Present Insp.- (Type 7):			0		.0
Other Insp.- (Type 8):			0		.0
Total of Types 3-8:			0		

F1=Help F2=Cancel F5=Pm F6=Diesel F9=PartI F10=Points